

**Interiors, Actuation & Propeller Systems**

UTC Aerospace Systems  
Piazza Arturo Graf 147  
10126 Torino  
Italy



**Marco D'Ascenzi**

Aftermarket Business Development Manager  
Actuation & Propeller Systems - UTC AEROSPACE SYSTEMS  
E-mail: marco.dascenzi@utas.utc.com  
Tel: + 39 366 653 2689

Turin, 16 May 2017

Aircraft Propeller Service, LLC Customer,

**Subject: License for repair of helicopter servo actuators in Brazil**

Dear Aircraft Propeller Service Customer,

Please be advised that Aircraft Propeller Service, LLC has been licensed by Microtecnica S.r.l., a UTC Aerospace Systems ("UTAS") Company to perform repairs on the following Main and Tail Rotor Servo Actuators models for AW109 helicopters operating in Brazil:

UTAS Part Number	Description
204-/205-/206-28007-00	Main Rotor Servoactuator
304-/305-/306-28007-00	Main Rotor Servoactuator
344-/345-/346-28007-00	Main Rotor Servoactuator
0-28013REVA	Tail Rotor Servoactuator

The license is effective on December 15, 2016.

Please contact Marco D'Ascenzi for any questions related to this license.

Yours sincerely,

A handwritten signature in blue ink, appearing to read "Jochem Peeters", with a long horizontal flourish extending to the right.

Jochem Peeters  
Head of Sales Planning and Business Development IATA2  
Interiors, Actuation & Propeller Systems  
UTC AEROSPACE SYSTEMS