

	CL215T/415	INSPECT / TEST	REPAIR	MAJOR INSPECTION / OVERHAUL
<b>Prop Model</b>	<b>14SF-19</b>	✓	✓	✓
<b>Propeller PN</b>	802375-2	✓	✓	✓
<b>Propeller Control Unit</b>	782490A15	✓	✓	REPAIR/CPI only - 5000 hours
	A26	✓	✓	REPAIR/CPI only - 5000 hours
	A37	✓	✓	REPAIR/CPI only - 5000 hours
	A48	✓	✓	REPAIR/CPI only - 5000 hours
<b>Hub</b>	794301-2	✓	✓	✓
	802228-1	✓	✓	✓
	802308-1	✓	✓	✓
<b>Actuator</b>	790180-2,3	✓	✓	✓
<b>Blade and Pin</b>	SFA13N1ROA-1	✓	✓	✓
	SFA13S1-OA-1	✓	✓	✓
	SFA13S1POA-1	✓	✓	✓
	SFA13S1ROA-1	✓	✓	✓
<b>Bulkhead</b>	784914-1,3	✓	✓	REPAIR only
<b>Retaining Ring</b>	802227-1	✓	✓	REPAIR only
<b>Spinner</b>	790176-1	✓	✓	REPAIR only
<b>Trans. Tube</b>	782515-1	✓	✓	✓
	814829-1	✓	✓	✓